

Quality Ticket	
<b>Serial Number</b>	M00000002
<b>Ticket</b>	420
<b>Module Info</b>	Lookup
<b>Application</b>	Get info
<b>Plant Number</b>	Close Quality Ticket
<b>Description</b>	
<b>Symptom</b>	
<b>Initiated By</b>	
<b>Process (Test Stage)</b>	OETI Test
<b>Symptom Category</b>	N/A
<b>Comment</b>	
<b>Process Step (Test)</b>	OETI Initialize Module
<b>Symptom</b>	N/A
<b>No Defect</b>	Defect
<b>Cancel/New</b>	Save
<b>Close</b>	
<b>Quality Ticket Explorer</b>	
<b>Alerts/Operations</b>	Current Operation: CIENAM module A, CIENAM module B

## Figure 9





140

70

80

90

50

75

85

7a

200

280

210

290

385

315

310

320

335

360

350

Defect/Action Information for Quality Ticket: 4895 [SN: M0000001; PN: 130-0466-900; Rev: 001]

Operator: CIENA\dmstestuser1

Process (Test Stage): OT1 - Px

Symptom Category: 1 N/A

Comment:

Area of Operation: 1DUg

Process Step (Test): RX grating test

Symptom: N/A

Defect

Defect Category:

Components:

Comment:

Action

Defect:

Troubleshooting Guide

Save

Component

To get the detailed information on each defect double click on the corresponding row or click on the Feedback button

Status	Defect Category	Defect	Reference Designator(s)
Not Fixed	Component Defects	Damaged	YERE, EEE
No Action	Component Defects	Damaged	tmdd
No Action	Component Defects	Damaged	GGG, DFDD, DDD
No Action	Component Defects	Damaged	

Feedback

Close

7

System Test

CIENA\dmstestuser1, CIENA\dmstestuser1

Figure 10b